



Attorney Docket No. 392.1840

CofC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Yasusuke IWASHITA, et al.

Application No.: 10/715,857

ATTENTION

Confirmation No.: 5602

CERTIFICATE OF CORRECTION

Filed: November 19, 2003

BRANCH

U.S. Patent No.: 6,879,130

Issued: April 12, 2005

For: CONTROLLER FOR INDUCTION MOTOR

**Certificate**  
**NOV 22 2005**  
**of Correction**

**REQUEST FOR CERTIFICATE OF CORRECTION**

Commissioner for Patents  
PO Box 1450  
Alexandria, VA 22313-1450

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date:

Nov. 17, 2005

By:

H. J. Staas

Registration No. 22,010

1201 New York Ave, N.W., Suite 700  
Washington, D.C. 20005  
Telephone: (202) 434-1500  
Facsimile: (202) 434-1501

NOV 23 2005

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.  
(Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE

## CERTIFICATE OF CORRECTION

PATENT NO : 6,879,130

DATED : April 12, 2005

INVENTORS : Yasusuke IWASHITA, et al.

Page 1, Item (73), change "Fanuc Ltd" to --FANUC LTD--;  
Column 3, line 14, change "12" to --1<sub>2</sub>--.

## MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP  
1201 New York Ave., N.W.  
Suite 700  
Washington, DC 20005

PATENT NO. 6,879,130

No. of add'l copies  
@ 50¢ per page

⇒

NOV 23 2005